



OMNI CONTROL DRIVER RELEASE NOTES

Omni Control Mac driver v1.6.6 fixes a bug in Mac OS 10.5.6.

Known issue of v1.6.6:

1. If OMNI CONTROL is connected to a Mac and the computer enters Sleep Mode, OMNI CONTROL must be restarted. Disconnect the OMNI CONTROL before allowing Mac to enter Sleep Mode or disable Sleep Mode entirely.